



# MOTOROLA SOLUTIONS

## Airwave Network Connection Concession Certificate HWFRS SEED SDS-MTA version 1.0.4.4

The following equipment (hereafter referred to as the "Equipment") has been reviewed by the Airwave Network Reference System for connection to the Airwave network.

	Manufacturer/Customer:	Versions:	Review Date:	Certificate Issue Date:
Supplier and Equipment Information	Hereford & Worcestershire Fire and Rescue Service  Hindlip Park  Worcester  WR3 8SP	Product Designation:-  Panasonic CF33 Brigid -v2.3.0.0  Main Component:-  Seed Short Data Router Service  Message TransferAgent v1.0.4.4  Related Software:-  Seed CNC Lite v1.1.1.0  Tested with TETRA Terminal Version:- Motorola MTM800E version MR5.13.1  Using Getac Dock:- Panasonic CF-VEK331NEP	03 Aug 2023	04 Aug 2023

The Equipment was reviewed for connection to the Airwave Network Reference System configured as follows:

<b>Airwave Network Software version: -</b>	<b>D9.0.2 and D7.1.2</b>
<b>Airwave/Customer Test Specification Title and Issue: -</b>	<b>Airwave Radio Connected Dispatcher Console Conformance Test</b>

The concession review conducted on the Equipment suggests that it will not adversely impact the Airwave Network (as configured in accordance with the above specifications) when connected and used. The review was limited to Conformance tests in accordance with the latest applicable specification and hence no specific functionality or performance of the product was considered unless specified below or in the test results.

**Key Observation/Comments:**

1. The initial Conformance testing was conducted on 7/10/20 on Panasonic CF33 running Brigid v2.0.1.0 and using Seed SDS MTA v1.0.4.0 This concession supplements the original certificate following changes to the software as defined in Seed Software Short Data Router MTA Release Notes for version 1.0.4.1 dated 5/10/2020.
2. No further conformance testing has been carried out and this Concession Certificate has been issued purely on the assessment of the submitted documents and declaration by Hereford and Worcester FRS.
3. Key changes in the release: - Fix to issue related to incorrect read location of configuration mapping files.

**Disclaimer:**

1. This conformance certificate does not indicate any security approval with respects to the operation of this hardware / software on the Airwave network.

It is the responsibility of the supplier and their customer (whether Airwave Solutions Ltd or 3rd party customer) to ensure the Airwave Accreditor's security requirements have been met before this hardware / software is deployed on the Airwave operational network. If this solution is deployed within the customer's security domain then the customers Accreditor / senior officer responsible for security must give their approval in line with the Airwave Service Code of Connection.

2. The issuing of this Connection Certificate is for information purposes only and Airwave makes no warranty representation (express or implied) or guarantee whatsoever as to the fitness for purpose of the Equipment or its ability to operate correctly when connected to the Airwave Network or any other network or equipment. Your use of the Equipment, connection of the Equipment to the Airwave Network and reliance on the contents of this Connection Certificate (for whatever purpose) is at your sole risk. To the fullest extent permitted by law, Airwave shall not be liable for any loss or damage (whether due to negligence or otherwise) arising in relation to the Equipment, its connection to the Airwave Network or any other network and/or your reliance on the content of this Connection Certificate.



Issued by: Philip Saunders.  
Principal Systems Test Engineer  
Email: [philip.saunders@motorolasolutions.com](mailto:philip.saunders@motorolasolutions.com)