

## Airwave Network Connection Certificate

The following equipment (hereafter referred to as the "Equipment") has been tested at the Airwave Network Reference System for connection to the Airwave network.

	Manufacturer/Customer:	Versions:	Test Date:	Certificate Issue Date:
Supplier and Equipment Information	<p>Motorola Solutions UK Limited, Nova South, 160 Victoria Street, London. SW1E 5LB.</p>	<p><b>Non-E2E Devices.</b></p> <p><b>Product / System Designation:-</b></p> <p><u>Vehicle Terminals</u> MTM5400 (inc. Refresh) MTM5500 (inc. Refresh) MTM5200</p> <p><u>Hand Portable Terminals</u> MXP600 (inc. Refresh) MTP6650 ST7000 / ST7500 TPG2200 MTP8500Ex / MTP8550Ex</p> <p><b>Software Version:</b> MR2021.3 non-E2E MTM5000 Series (Part No. R27.020.9689 / R14.000.9689). MXP600 (Part No. R55.020.9689) MTP6650 (Part No. R33.020.9689). ST7000 Series (Part No. R37.020.9689). TPG2200 (Part No. R38.020.9686). MTP8500Ex Series (R36.020.9689).</p>	<p>15 Feb 2022 To 21 Apr 2022</p>	<p>05 May 2022</p>

---

At the time the Equipment was tested the Airwave Network Reference System was configured as follows:

<b>Airwave Network Software version: -</b>	<b>D7.1.2 / D9.0.2</b>
<b>Airwave/Customer Test Specification Title and Issue: -</b>	<b>Airwave Radio Test Spec Version 5.1 (incl. OTAR, C-SCCH &amp; eTetra), excluding Ambulance Specific Tests.</b>

	<b>Mandatory Tests</b>	<b>Optional Tests</b>	<b>Drive Test</b>	<b>Additional Tests (See Notes)</b>
Test Results	<b>Pass</b>	<b>Pass</b>	<b>N/A</b>	<b>N/A</b>

The testing conducted on the Equipment suggests that it will not adversely impact the Airwave Network when connected and used (as it had been configured and tested during certification in accordance with the above specifications). Test scope was limited to conformance tests in accordance with the latest applicable specification and hence no specific functionality or performance of the product was tested unless specified below or in the test results.

**Key Observation/Comments:**

1. The Terminals are NOT Certified for installation and/or use within an Aircraft.
2. The MTM5200 Terminal has also been given approval on the basis of Software commonality with the MTM5400 & MTM5500 Terminals.
3. The Legacy & Refresh MTM5000 series Radio Terminals are covered under this Certificate.
4. The Legacy & Refresh MXP600 Radio Terminal is covered under this Certificate.
5. Note, the MR2021.3 software part number for the TPG2200 is different from all the other Radio Terminals in the range.


---

**Disclaimer:**

1. This conformance certificate does not indicate any security approval with respects to the operation of this hardware / software on the Airwave network.

It is the responsibility of the supplier and their customer (whether Airwave Solutions Ltd or 3rd party customer) to ensure the Airwave Accreditor's security requirements have been met before this hardware / software is deployed on the Airwave operational network. If this solution is deployed within the customer's security domain then the customers Accreditor / senior officer responsible for security must give their approval inline with the Airwave Service Code of Connection.

2. The issuing of this Connection Certificate is for information purposes only and Airwave makes no warranty representation (express or implied) or guarantee whatsoever as to the fitness for purpose of the Equipment or its ability to operate correctly when connected to the Airwave Network or any other network or equipment. Your use of the Equipment, connection of the Equipment to the Airwave Network and reliance on the contents of this Connection Certificate (for whatever purpose) is at your sole risk. To the fullest extent permitted by law, Airwave shall not be liable for any loss or damage (whether due to negligence or otherwise) arising in relation to the Equipment, its connection to the Airwave Network or any other network and/or your reliance on the content of this Connection Certificate.



Issued by: Philip Saunders.  
Principal Systems Test Engineer  
Email: [Philip.Saunders@motorolasolutions.com](mailto:Philip.Saunders@motorolasolutions.com)