



MOTOROLA SOLUTIONS

Airwave Radio/Network Connection Certificate

The following equipment (hereafter referred to as the "Equipment") has been tested at the Airwave Network Reference System for connection to the Airwave network.

	Manufacturer/Customer:	Versions:	Test Date:	Certificate Issue Date:
Supplier and Equipment Information	<p>Handsfree Group</p> <p>6 Lumsdale Road, Cobra Court, Trafford Park, Manchester M32 0UT</p> <p>Tel: 01618 646440</p>	<p>Product / System Designation:-</p> <p>Handsfree Group R5</p> <p>Software Version:</p> <p>R5 D2D System App: 1.13.1</p> <p>Certified and Tested with TETRA</p> <p>Terminal Version:</p> <p>Motorola MTM 800E V5.13.1 build Motorola MTM 800E V5.14.9C build Motorola MTM 5400 V2022.2 build Motorola MTM 5400 V2022.4 build Motorola MTM 5500 V2022.2 build Motorola MTM 5500 V2022.4 build</p> <p>Other Information/Approvals</p> <p>MTM 800E radios were conformedanced with a connected Junction box and are not certified for use without a Junction box</p>	<p>14 Jun 2023</p>	<p>05 Jul 2023</p> <p>This certificate expires on 05 Nov 2023</p>

At the time the Equipment was tested the Airwave Network Reference System was configured as follows:

Airwave Network Software version: -	Motorola Dimetra v 9.0.2
Airwave/Customer Test Specification Title and Issue: -	Radio Connected Dispatch Console Generic Test Plan

The testing conducted on the Equipment suggests that it will not adversely impact the Airwave Network when connected and used (as it had been configured and tested during certification in accordance with the above specifications). Test scope was limited to conformance tests in accordance with the latest applicable specification and hence no specific functionality or performance of the product was tested unless specified below or in the test results.

Key Observation/Comments:

1. MTM800E - Emergencies sent from dispatcher will not display on R5 headunit until PTT is activated by a user within the talkgroup
2. All models - After cable disconnects scenarios remedial action is required to restore full functionality and correct status

Disclaimer:

1. This conformance certificate does not indicate any security approval with respects to the operation of this hardware / software on the Airwave network.

It is the responsibility of the supplier and their customer (whether Airwave Solutions Ltd or 3rd party customer) to ensure the Airwave Accreditor's security requirements have been met before this hardware / software is deployed on the Airwave operational network. If this solution is deployed within the customer's security domain then the customers Accreditor / senior officer responsible for security must give their approval in line with the Airwave Service Code of Connection.

2. The issuing of this Connection Certificate is for information purposes only and Airwave makes no warranty representation (express or implied) or guarantee whatsoever as to the fitness for purpose of the Equipment or its ability to operate correctly when connected to the Airwave Network or any other network or equipment. Your use of the Equipment, connection of the Equipment to the Airwave Network and reliance on the contents of this Connection Certificate (for whatever purpose) is at your sole risk. To the fullest extent permitted by law, Airwave shall not be liable for any loss or damage (whether due to negligence or otherwise) arising in relation to the Equipment, its connection to the Airwave Network or any other network and/or your reliance on the content of this Connection Certificate.



Issued by: Glen Conway.
Senior Engineering Test Manager
Email: glen.conway@motorolasolutions.com